




Failure Analysis Report

<i>I. AOS Report</i>				
FA No: CR07A0012		Report Date: Jan 8, 2007		
Customer FA No: VIT71010.50		Manager: Zhiqi Wang		
Requested By: Chih Hung Yu		FA Engineer: Ni Di		
<i>II. Product Information</i>				
Part Number: AO4612		No. of Unit returned: 1		
Package Type: SOP-8		MOSFET Type:		
<i>III. Customer Information</i>				
Customer: Logah		Customer Return Date: Jan 8, 2007		
Reason(s) for return: AO4612 GDS short				
<i>IV. Initial Observation</i>				
Product Status: Mass Production		Application: DC-AC		
Functional Failure Occur During: StartUp		Manufacture Failure Occur During: Steady-State		
Failure Found At: one-reel		Total No. of units used: 32767		
Total No. of units failed: 1		Failure Rate(%): 0.0031		
Same Date Code?: Yes		Did the circuit work again after replacing the failed unit with another part?: Yes		
FAE Comments:				
<i>Parts Detail</i>				
#	Marking	Date Code	Failure Mode	Visible Damage
1	BA6F11	6F	GDS	No

V. Package Visual Inspection

One unit was returned for failure analysis.

SN1



Pin4 lead bend was observed.
Solder and flux were observed on the external leads.

VI. Testing and Failure Verification

ATE testing:

The unit was ATE tested and verified in curve tracer for device characteristic.

die1:	MOSFET N-channel	Igss A	Igssr A	Idss A	Bvdss V	Vgsth V	Confirm in curve tracer
	Spec. max	8.00E-08		1.00E-07	90.0	2.7	
	min		-8.00E-08		61.0	2.0	
	SN1	1.00E-04	-1.00E-04	1.00E-03	3.4	0.0	GDS short

die2:	MOSFET P-channel	Igss A	Igssr A	Idss A	Bvdss V	Vgsth V	Confirm in curve tracer
	Spec. max		8.00E-08		-61.0	-1.7	
	min	-8.00E-08		-1.00E-07	-80.0	-2.3	
	SN1	-1.00E-04	1.00E-04	-1.00E-03	0.0	0.0	GDS short

Note: * denote measurements at the compliance limits


Results:

The unit failed due to GDS short on both die.

VII. Physical Analysis

The failed unit was decapped for further analysis.

SN1



Note: Melted metal & burn mark were found on source active region.

VIII. Discussion

Summary of observations

Observation:	One unit was returned from Logah for failure analysis. Pin4 lead bend was observed. Solder and flux were observed on the external leads.
Identified failure mode:	The unit failed due to GDS short on both die.
Decapsulation:	The failed unit was decapped for further analysis. Melted metal & burn mark were found on source active region.

Possible root causes

EOS	<p>The observed carbonized molding compound and alloyed / discolored metal on the active region are typical result of electrical overstress(EOS) due to high current flow and the associated high heat generation. This indicated that the device might operate out of safe-operating-area (SOA) which caused the electrical overstress damage.</p> <p>In general, the high heat that carbonization need is caused by high current flow in device and the over heat will drive the temperature up to the burning point of molding compound and make it carbonized or make metal on the device melted.</p> <p>Review of the wafer and final test yield summary showed that the shipped units with the yield above the average and passed both AOS outgoing final test and QA screen. AOS acknowledge the failure observed by the customer and appreciate the customer's time and effort to help AOS responding the suspected issue and correct some deficiency. However, the obvious symptom of root cause could be masked out by burnt mark/carbonized molding compound, AOS has recorded this reported failure using a tracking no. For just one failure was returned from customer, it also could be an infant mortality or random failure. Should the units continue to fail, Logah may consult with AOS application engineer for further assistance.</p>
-----	--

Corrective action

--	--