

Can the options be retrofitted on the 53131A/53132A/53181A and 53200 Series counters?

Upgrade/retrofit kits are available for all options for 53210A, 53220A or 53230A frequency counters.

For 53131A, 53132A, or 53181 frequency counters, parts for option retrofits can be ordered. For complete details and parts required, please see the service note that applies to your products:

- Service Notes for [53181A](#)
- Service Notes for [53131A](#)
- Service Notes for [53132A](#)

Option	53181A	53131A	53132A	Note
001	✓	✓	✓	May be installed by customer or service center. Only one timebase option may be installed in a unit. Unit with firmware version less than 3402 will need an upgrade.
010	✓	✓	✓	
012	✓	✓	✓	
015	✓			May be installed only at an Keysight service center. Unit may only have one of these third-channel options installed at a time.
030	✓	✓	✓	
050	✓	✓	✓	
124	✓	✓	✓	
060	✓	✓	✓	May be installed by customer or service center on units that do not have option 002.

Learn more about [Keysight 53200 Series RF & Universal Frequency Counter / Timers \(350 MHz\)](#)

Was this helpful?

Yes

No

Didn't find what you're looking for?

Contact Support

EXPLORE

Products + Services

Solutions

Industries

Events

Learn

Used Equipment

INSIGHTS

Discover Insights

Success Stories

Resources

Blog

Community

PARTNERS

SUPPORT

Product Support

Manage Software

Licenses

Product Order

Status

Parts

ABOUT KEYSIGHT

Newsroom

Investor Relations

Quality and
Security

Corporate Social
Responsibility

Diversity, Equity,
and Inclusion

Modern Slavery Act
Transparency
Statement

Careers

