

3458A-19A

S E R V I C E N O T E

Supersedes:
3458A-19

3458A Multimeter

Serial Numbers: ALL (exception H11/K11 see bottom of next page)

The original 3458A A5 (PC Assy-Outgard Controller) is no longer available. The replacement kit consists of two unique parts and an installation note.

Parts Required:

P/N	Description	Qty.
03458-80047	Update Kit for standard 3458A A5 assembly	1
03458-80048	Update Kit for extended memory 3458A A5 assembly	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY
AUTHOR: LH PRODUCT LINE: SP
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2007
PRINTED IN U.S.A.



April 10, 2007

Situation:**Replacement kit 03458-80047**

Replacing the A5 (PC Assy-Outguard Controller) requires replacing the 03458-66505 standard PCA with the new 03458-66547 standard PCA. Each kit contains the new A5 PC Assy-Outguard controller, 1 cable, and an installation note.

Replacement kit 03458-80048

Replacing the A5 (PC Assy-Outguard Controller) requires replacing the 03458-66515 extended PCA with the new 03458-66548 extended PCA. Each kit contains the new A5 PC Assy-Outguard controller, 1 cable, and an installation note.

* **03458-80048** kit can be used with all 3458A models: in addition to replacing the A5 PC Assy-Outguard controller this kit will upgrade the memory converting any standard 3458A to a 3458A-001.

Solution/Action:

Please order the new kits and follow the installation note.

H11/K11

Customers who have this special option **MUST** continue to order the 03458-66505/66515.